



FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management

Solid Waste Section

UNIT TYPE:											
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

COUNTY: Alexander
PERMIT NO: SLAS-02-04
FILE TYPE: COMPLIANCE

Date of Site Inspection: October 25, 2012

Date of Last Inspection: August 8, 2012

FACILITY NAME AND ADDRESS:

Taylorsville Precast Molds, Inc.
Henry Road
Taylorsville, NC 28681

GPS COORDINATES: N: 35.88222 W: 81.12165

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: David R. Mecimore
Telephone: (828) 632-4608
Email address:

FACILITY CONTACT ADDRESS:

128 Taylorsville Mfg. Road
Taylorsville, North Carolina 28681

PARTICIPANTS:

Charles Gerstell, NCDENR-Solid Waste Section

STATUS OF PERMIT:

Active

PURPOSE OF SITE VISIT:

Routine Inspection

STATUS OF PAST NOTED VIOLATIONS:

None

OBSERVED VIOLATIONS

N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.


FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. This inspection was performed to collect soil samples from the septage land application field. A check was received for the NCDA & CS.
2. Proper signage was provided at the entrance to the facility. A second sign was provided on the east side of the property adjacent to Henry Road.
3. The access road leading to the site was off all-weather construction.
4. The disposal boundaries were marked with white PVC pipes located at each corner of the application field. Dense vegetation surrounding the markers during the previous inspection had been cut back.
5. The field had a good stand of vegetative cover at the time of inspection.
6. No evidence of runoff or application outside of the approved area was observed.
7. No evidence of rutting was observed.
8. No objectionable odors were observed during the inspection.
9. It appeared that all setbacks were being maintained.
10. The application field had recently been harvested. Hay bales were on site at the time of the inspection.

Please contact me if you have any questions or concerns regarding this inspection report.


Charles T. Gerstell
Environmental Senior Specialist
Regional Representative

Phone: (704) 235-2144

Sent on: <u>10/29/12</u>		Email		Hand delivery	<input checked="" type="checkbox"/>	US Mail		Certified No. <input type="checkbox"/>
--------------------------	--	-------	--	---------------	-------------------------------------	---------	--	--

Copies: Jason Watkins, Western District Supervisor
Tony Gallagher, Composting & Land Application Branch Head
Becky Whetstone, Office Assistant, Composting & Land Application Branch